Present and Future of RESNET Quality Assurance

Scott Doyle and Laurel Elam, RESNET



Presentation Agenda

- Current Status of Addendum 29
- Status of Other Quality Assurance Changes
- Current Quality Assurance Program and Staff
- Future of RESNET Quality Assurance Program
- Questions





Setting the Standards for Home Energy Efficiency





Addendum 29

- A working group of the SDC 900 reviewed the 27 comments submitted
- Several comments submitted were to strike the sections on creating direct and third-party providers completely
- SDC 900 will request that the Board of Directors revise their original policy on the financial separation of QAD and providers providing rating services



Policy, Amendments & Implementation


- The RESNET Board approves the policy
- The policies are implemented in the RESNET Standards through amendments
- SDCs review public comments and approve the responses to the comments
- RESNET staff enforce the RESNET Standards



Addendum 29

Addendum 29 was released for public comment and only included:

- Creation of Direct and Third Party Rating Providers
- Creation of Quality Assurance Agents





New Provider Models

Direct Providers

Do ratings in-house

Third-party Providers

Do not do ratings in-house





Quality Assurance Agents

Anyone doing quality assurance for RESNET will become "Agents of RESNET" and will be trained.





Why a smaller QA Amendment?

- Changes were lost in the larger amendment
- Help facilitate the consideration and adoption





Let's Go Back to 2013





What was the reason for making these changes?

RESNET Board Analysis Found


- Inconsistency of quality assurance oversight by Rating Providers
- Inconsistency of the way the various software programs allowed variance of raters in inputting data into the program
- Inconsistency of Home Energy Rater candidate testing





Chapter Two

- Amendments to chapter two require:
 - Rater candidates to take rater training so they can no longer challenge the rater exam
 - All five probationary ratings are conducted with a rating provider and overseen by a candidate field assessor





Software

Policies adopted at the 2013 Fall Board meeting

- RESNET incorporate changes to rating software standards that would include:
 - Establish limits on input variables for whole-house ventilations systems and other in the RESNET Standards
 - Determine bounds checks that can be incorporated into software to limit or warn users when input values are beyond reasonable limits
 - Enhance rating software tools to enable flags to be set for internal inconsistencies that should be checked prior to entering a building file into RESNET registry



Software- More work to do!

- HERS Software Consistency Task Group has been created and includes representatives from all of the software vendors
- Session "HERS Consistency A Discussion from a Software Perspective" at 3:30 PM today Grand Salon I
- This session will be a review of their findings and recommendations





Fall 2013 RESNET Board Meeting

Approved the following policies

- RESNET certified Quality Assurance Designees must in the future:
 - Serve as agents of RESNET
 - Have neither a financial interest nor an employee/employer relationship with the entity performing the rating





What has changed since then?

- The Registry wasn't being utilized fully for QA report reviews until 2014 because 2013 was the first year of complete data
- Since 2013 there have been drastic improvements in the implementation of RESNET QA standards
- QA Genie is now being used





Enhancing the Consistency of HERS Index Scores

Goals for RESNET Quality Assurance

- Consistency in the ratings completed by Raters
- Consistency in Quality Assurance






Setting the Standards for Home Energy Efficiency

What is the solution?

- Does the proposed solution of financially separating QADs from Providers address the inconsistent QA processes, interpretations, and enforcement of standards?
- Can this be addressed through training of both QADs, Raters and RFIs?







Other changes to QA Standards

- Other changes to the QA standards are on hold until a decision can be made by the RESNET Board
- Once a decision has been made other changes may be required before it goes out for public comment again





RESNET QA Today

We are building our QA Team!

- Scott Doyle joined RESNET in July 2017 as Quality Assurance Manager
- Addition of other RESNET Staff
- Will be adding an Infield QA Specialist in 2018





RESNET QA Today

- Improvement in annual QA reports and enforcement of the RESNET QA standards.
- Fewer providers being placed on probation for not meeting the annually required file and field QA review requirements
- Now have the ability to track QA in the Registry





Online QA Reviews

Online Reviews are Viewed as Positive

File Review Process

Using QA Genie





Online QA Reviews

Only 1-in-4 Providers are reached annually

Only the Primary QAD joins the call

Does not include in-field mentoring or

monitoring





QA Genie

Want to know more about the findings from QA Genie?

Session "The Genie is out of the Bottle! What we have Learned so far from QA Genie"

Wednesday 1:30 PM Grand Salon VII



Setting the Standards for Home Energy Efficiency





Future of RESNET QA


- Improvements in Past Several Years
- Still Discovering Inconsistencies
- RESNET needs to have a presence in the field working with QADs and providers





What do the Standards Say?

Section 902.1 RESNET shall select a <u>minimum</u> of 25% of accredited QA Providers and conduct a more detailed review of their Quality Assurance records.





Plans for 2018

50% of Providers and their QADs will have enhanced RESNET QA Annually

- 25% Online Review
- 25% In-Field Review





Plans for 2018

Train All QADs and Delegates

Quarterly Webinar Series





Plans for 2018

Train All QADs and Delegates

Introduce the new Field/File QA Checklist

QAD Roundtable-

Tuesday 2:15 PM Grand Salon I

	RESNET Field & File Checklist					
	Plating wart be	corrected and aimstation file resubmitted to Registry if: 1) say item with an set	trick (") is incorrect, or 2) se	ny itom is giron a so	urity record of "3", or 3) the orienal rating is a "FAL".	
				PASS	Pass/Fail Threshold = 91	
tem '	Field / File	Checklist Item	"OK" or, if item is incorrect, indicate the "Severity" (1 = Low, 2 = Mediem, 3 = High)	Score:	Comments	
1.	Field / File	The address is not duplicated in the Registry.				
2.	Field / File	The address is correct and complete for the rated home.				
3.	Field / File	The Rate:IRFI matches the RTINRFIN.			•	
4.	Field / File	Climate location is correct for the rated home				
5.	Field / File	Utility rates are correct and complete for the rated home.				
6.	Field / File	The Rating Date is properly assigned for the rated home.				
7	Field / File	The Rater provided a signed Standard Disclosure Form (Myhen required).				
8	Field / File	All Warning Flags generated by the software were addressed by the Rater.				
9	File	The Sampling Process is correct as required by 904.4.1.3.4.1				
10*	Field / File	Required Documentation v as provided to support the minimum rated features modeled, as defined by RESNET Standards, i.e., a take-off is from plans for projected ratings or field sketches for existing homes; Energy-Guide labels for appliances; AHRI certificates for HVAIC equipment, NRIC or spec sheets for vindor performance values; etc.).				
11"	Field / File	The HERS Index is within acceptable variance, as defined by the RESNET Standards.				
12*	Field / File	The number of bedrooms match the site data collected and/or projected specifications.				
13*	Field / File	Number of stories, including basement, match on-sitelfile.				
14	Field / File	The envelope ceiling area≥ the envelope floor area.				
15	Field / File	The Rater indicated vaulted or sloped ceilings if the envelope ceiling area is > envelope floor area.				
16	Field / File	The average ceiling neight is reasonable and match the sixedata collected and/or projected specifications. (For example: Divide the conditioned volume of the home by the conditioned floor too.)				
17	Field / File	The above grade viall height is reasonable and close to the average ceiling height. (For example: Multiply the foundation perimeter by the number of stories. Divide the above grade vial area by that result to get the approximate vial height)				
18	Field / File	The areas, types, and locations match the site data collected and/or projected specifications for flat, vauled/sloped, and/or encapsulated cellings. The celling pitch of a lausted or sloped celling is reasonable.				
19	Field / File	(Example: If vaulted or sloped ceilings are in the simulation file, subtract flar ceiling from footprint. Divide the sloped/vaulted ceiling area by that result and multiply by 12 to determine the pitch.				
20	Field / File	The foundation type(s) match the site data collected and/or projected specifications.				
21	Field / File	The foundation wall area, type, and exposure match the				




Questions?

Scott Doyle

scott@resnet.us

Laurel Elam

<u>laurel@resnet.us</u>









Setting the Standards for Home Energy Efficiency